Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8665 Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Cover Sheet

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



06 Mar 2025 06 Mar 2026 12 Annual Re-Assessment Type 3 (Common Parts and Flats - Non Destructive) Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Cross Banks
Scheme Address	Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford
Postcode	BD6 1RA
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	House Mobile 07767003560
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	Duty staff 24/7
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Carers

The Building

Accommodation Type	Supported Housing (S50)
Build Date	Jan 1 1971
Number Of Homes	5
Homes breakdown	Room
External wall construction	Facing Brick
External wall finish	Insulation Render
Roof construction	Timber
Roof covering	Interlocking Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Conversion
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	One protected
Number of External Staircases	One
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas linked
Grade of fire alarm	Grade D
Category of fire alarm	LD2 Additional Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Asset ID: 8665

Number of occupants	2
Occupant tenure type breakdown	Supported Housing, Supported Housing Hostel

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	0
Overdue Annual Emergency Lighting tests	0
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment
FRA Frequency (Months)
Purpose of Fire Risk Assessment
Type of Risk Assessment
Quantity
Fire & Safety Assessor
Enforcing Fire Authority
Scheme Tel. No
Other staff in attendance
Number of on-site Accent staff
Number of other (non-Accent) staff
Scheme Inspection completed
Number of occupants
Personal Emergency Evacuation Plans in place
Current Evacuation Strategy
Conversion or purpose-built
Number of Storeys
Number of floors on which car parking is provided
Is there a habitable basement?
No. of internal staircases (protected/unprotected)
Number of external staircases
External balcony part of escape route?
Unusual features



West Yorkshire House Mobile 07767003560

Duty staff 24/7

None

Carers

Yes

2

Yes

Full (Simultaneous) Evacuation

Conversion

2

0

No

One protected

One

No

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas linked
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD2 Additional Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	Yes
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	Yes
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good conditi obvious damage?	ion and no	Yes
Comment		All in good conditionm at th time of inspection.
Valid Electrical Installation Condition Reports held on file? Areas & General Needs Flats)	? (Common	Yes
Comment		Last test date : - 27/09/2023
Electrical App/PA Testing - tested within past 12 months?		Yes
Comment		All equipment has a PAT Label Test Date : - 04/10/2024
Absence of trailing leads and adapters?		Yes
Comment		None found at th time of inspection.
Evidence that mobility scooters are not being stored/charg common areas?	ged in	Yes
Comment		None on Scheme.
Is there a purpose built mobility scooter store/charging are	ea?	No
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 17	Generated 07/03/2025 16:02:36

Comment	Not required.
Does the building have a lightning protection system?	No
Comment	

Gas installations

Asset ID: 8665

Is there a commercial/domestic gas supply to the scheme?
Comment
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)
Comment
Valid LGSR held on file for residential flats that contains gas appliances?
Comment
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to? Comment
Adequate security against arson?
Comment
Are refuse/recycling bin areas managed and suitably located?
Comment
Are there communal cooking facilities at this scheme?
Comment
Are reasonable measures taken to prevent fires as a result of cooking?
Comment
Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly? Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?

Yes
The property has a gas central heating boiler.
Yes
Gas certificate last test date :- 08/07/2024 N/A
not required for indiuvidual rooms.

N/A

THe detectors are tested at the time of the gas certificate.

Yes

There is a no smoking policy throughout the building

Yes

there is an intercom system at the main entrance. CCTV is also in opperation.

Yes

Bins are stored away from the building

Yes

THer is a kitchen that is used by the residents. Staff supervise the cooking of meals.

Yes

As above staff supervise the cooking of meals.

N/A

None fitted

Yes

Asset ID: 8665 Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Comment

Are unnecessary accumulations of combustible materials or waste avoided?

Comment

Are combustible materials and substances separated from ignition sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly?

Comment

Reasonable distances of travel where there is a single/alternative direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

None found at th time of inspection.

Yes

Nothing found at th time of inspection.

Yes

Nothing found at th time of inspection.

Yes

All furniture had the correct labeling at th time of inspection.

Yes

Nothing found at th time of inspection.

Yes

Ther is a protected internal staircase and an external staircase providing means of escape from the upper floor.

No

There are items on the staircase that need removing and coats at the bottom of the stairs that have been highlighted in the past. Duty officer informed. Yes

Yes

Distances are within the guidelines.

Yes

Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Observation	Priority	Referred To	Required By:	Task ID

external means of escape



Observation	Priority	Referred To	Required By:	Task ID
Fire exit on first floor leading to external stairs requires new door and frame. Push bar to open	Repair - Non Emergency	Project Manager (Building Safety)	16/05/2025	1929772
		MANY SWEET AND MANY A		





Observation

Fire exit on first floor leading to external stairs requires new door and frame. Push bar to open

Repair - Non Emergency


Priority

Project Manager (Building Safety)

Referred To


Required By: Task ID 1929772 30/04/2025





Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford


Observation	Priority	Referred To	Required By:	Task ID
Items on stairs require removing. Coats on coat hooks need removing from means of escape. duty staff informed	Internal - Medium	Independent Living Coordinator	16/05/2025	1929772





Observation	Priority	Referred To	Required By:	Task ID
Items on stairs require removing.	Internal - Medium	Independent Living	30/04/2025	1929772
Coats on coat hooks need removing from means of		Coordinator		

escape. duty staff informed





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

Yes
all of good standard at the time of inspection.
No
Ther is a notice board in the kitchen that requires a glass fronted lockable board. N/A
None fitted.

N/A

No access to roof space at the time of inspection.

Yes

Asset ID: 8665 Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Communal fire door at top of steps, ease and adjust	Repair - Non Emergency			
Observation	Priority	Referred To	Required By:	Task ID
Comment		None fitted.		
Are roller shutter doors that are required to be FR, fire resist self-closing?	ting and	N/A		
Comment		None fitted.		
If Smoke Control Systems (AOV's) are fitted, are the records testing available?	s of annual	N/A		
Comment		Traditionaly built brick w	vith slate roof.	
Do external walls, doors, windows and anything attached to exterior, limit fire spread?	the	Yes		
Comment		No cross corridor doors		
As far as can be reasonably ascertained, is the fire stopping cross corridor fire doors within suspended ceiling void of a s standard?		N/A		



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards? Comment	Yes
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	All units were in good condition at th time of inspection.
Records of monthly/annual testing available?	Yes
Comment	Tests are carried out by our contractors and recorded in ActiveH and M-Files. Last test dates. Annual drop test :- 30/04/2024 monthly test date : - 04/03/2025
Eiro Safaty Signa and Nationa	

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Comment	Notices are displayed throughout the building.
Directional fire escape signage in place and adequate?	Yes
Comment	As above
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	No lift fitted at this scheme.
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	

Means of giving Warning in case of Fire

Asset ID: 8665

Yes
Yes
This is a full evacuation system with a fire panel, call ppoints detectors and sounders
Yes
All tests are carried out by Tunstall, records are available in ActiveH and M-Files. Last test dates: - 6 Monthly : - 12/11/2024 Weekly : - 04/03/2025
Yes
All components in good condition at th time of inspection.
Yes
All in working order at th time of inspection.
Yes
Νο
Staff are on site while residents are at home, staff sleep over

Observation	Priority	Referred To	Required By:	Task ID
Fire panel				



Fire Extinguishing Equipment

Asset ID: 8665

Is fire extinguishing equipment and/or fixed fire fighting in provided at this scheme?	stallations	Yes		
Comment				
Portable fire extinguishers - appropriate type/number/pos	ition?	Yes		
Comment				
Correct signage displayed by each fire extinguisher?		Yes		
Comment				
Fire blanket in communal kitchen, secured to the wall, con signage?	mplete with	Yes		
Comment				
Dry risers - Inlet/outlet boxes secured and/or securing stra outlet valves?	aps fitted to	N/A		
Comment		None fitted.		
Records available of fire fighting equipment servicing with months?	nin past 12	Yes		
Comment		Records are available in N on each fire extinguisher.	I-Files, there is a te	est label
Observation	Priority	Referred To	Required By:	Task ID

Water extinguisher





Management of Fire Safety

No
Yes
Yes
A copy of the Fire risk Assessment will be sent to Affinity trust for their rcords.
N/A
Yes
As above.
Email and printed copy if requested.
No
No
No
Yes
The staff are instructed to dial 999 and ask for the fire service.
Yes

Engagement with Residents

Asset ID: 8665 Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Has information of fire procedures been disseminated to residents?	Yes
Comment	The staff have regular toolbox talks with the residents.
Is general fire safety information disseminated to residents?	Yes
Comment	As above.
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	Νο
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment?	Yes

Unauthorised items were found in communal areas and arrangementsYeswere made for their removal.NoNot all records were up to date, as noted in the table below.NoArrangements have been made for these to be completed.NoA number of fire doors were found to be wedged or propped open . Fire
doors are there to keep you safe and me kept shut at all times.No

Observation	Priority	Referred To	Required By:	Task ID

Yes

Yes

PAT Test Label

with our contractors.

contractors.

(Visible on Building Safety Report).



Some fire doors did not fully close so works orders have been raised

Some minor works were required which have been raised with our

Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Observation	Priority	Referred To	Required By:	Task ID

Refuse area



Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	нідн	
-----	---	--------	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Blk1 Group Home 2 Northfield 2 Northfield Road, Bradford

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial	